











DO NOT USE ANY TYPE OF BLEACH OR STAIN REMOVING CHEMICALS BEFORE OUTTING / STITCHING , FABRIC SHOULD BE SDAKED BE SDAKED IN WATER (ALL COMPONENTS SEPARATELY) FOR 15 MINUTES DO NOT KEEP WET FABRIC IN TWISTED FROM IN ORDER TO AVOID COPY MARKS I WASH COLOURED AND WHITE FABRICS SEPARATELY

IRON CLOTHES AT MODERATE TEMPERATURE I DO NOT DRY FABRIC IN DIRECT SUNLIGHT
(EXTRA LACES, HANGINGS AND ACCESSORIES ARE NOT INDUDED)

