

Fepic®



TEXTILE DEAL

WASHING INSTRUCTIONS

DO NOT USE ANY TYPE OF BLEACH OR STAIN REMOVING CHEMICALS
BEFORE DRYING / STEAMING. FABRIC SHOULD BE SOAKED IN WATER
(ALL COMPONENTS SEPARATELY) FOR 15 MINUTES.
DO NOT KEEP NET FABRIC IN TWISTED FORM IN DRYER TO AVOID COFFY MARKS ()
WASH COLOURED AND WHITE FABRICS SEPARATELY.
IRON CLOTHES AT MEDIUM TEMPERATURE (DO NOT DRY FABRIC DIRECT SUNLIGHT)
(EXTRA LABEL, HANGTAGS AND ACCESSORIES ARE NOT INCLUDED)

D-5171 B



Fepic®



TEXTILE DEAL

WASHING INSTRUCTIONS

DO NOT USE ANY TYPE OF BLEACH OR STAIN REMOVING CHEMICALS
BEFORE CUTTING / STITCHING, FABRIC SHOULD BE SOAKED IN WATER
(ALL COMPONENTS SEPARATELY) FOR 15 MINUTES

DO NOT KEEP WET FABRIC IN TWISTED FORM IN ORDER TO AVOID COPY MARKS |
WASH COLOURED AND WHITE FABRICS SEPARATELY

IRON CLOTHES AT MODERATE TEMPERATURE | DO NOT DRY FABRIC IN DIRECT SUNLIGHT
(EXTRA LACES, HANGINGS AND ACCESSORIES ARE NOT INCLUDED)

D-5171 D





D-5171 B



D-5171 D

TEXTILE DEAL

Fepic®

 :_Fepic

 :Fb.com/Fepic11